



Factory Preventative Maintenance

Airon Corporation recommends that all **pNeuton** Ventilators and **MACS** CPAP Systems receive preventative maintenance every 2 years. This service procedure is designed to ensure proper performance of the device throughout its expected life.

A complete Preventative Maintenance (PM) procedure includes:

- Installation of the PM kit which contains various components including tubing, filters, check valves and reed alarm
- Cleaning internal and external surfaces
- Complete inspection of the device
- Component update, if necessary, to current specifications
- Replacement of any defective parts not included in the PM kit*
- Calibration and testing to meet factory specifications

All PMs are performed by Airon Corporation at the Melbourne, FL facility. Purchase orders for the preventative maintenance must be issued in advance. Upon receipt of a purchase order, a Returned Goods Authorization Number (RGA) will be issued for the unit to be shipped to Airon. No device will be accepted without a properly issued RGA number. Please contact Technical Services at **1-888-448-1238** or technicalsupport@AironUSA.com to schedule a PM and obtain an RGA.

Prices**:	pNeuton S Preventative Maintenance	\$ 700.00 – Part Number 70201
	pNeuton A Preventative Maintenance	\$ 900.00 – Part Number 70211
	MACS CPAP Preventative Maintenance	\$ 225.00 – Part Number 70221
	pNeuton mini Preventative Maintenance	\$ 1100.00 – Part Number 70231
	pNeuton mini NEO Preventative Maintenance	\$ 1100.00 – Part Number 70251

Shipping is at the cost of the customer. Upon receipt of the device, we average a five business day turn around for the maintenance and performance testing. Please verify the estimated service time when requesting a RMA with your purchase order. Loaners are available if desired, at an additional cost**.

pNeuton S Loaner	\$ 200.00 – Part Number 70070
pNeuton A Loaner	\$ 250.00 – Part Number 70071
MACS Loaner	\$ 125.00 – Part Number 70072
pNeuton mini Loaner	\$ 450.00 – Part Number 70073
pNeuton mini NEO Loaner	\$ 450.00 – Part Number 70075

Terms and Conditions are subject to change at any time without notice.

* If any defective parts are found during testing you will be notified to obtain authorization for replacement. The cost of parts will be an additional charge. Labor to replace the parts will be waived if performed at the same time as the PM.

** All established pricing is listed for USA only

Airon Corporation
751 North Drive, Unit 6, Melbourne, FL 32934 USA
tel (321) 821-9433 fax (321) 821-9443

CD-O-040 Rev K